



Photo 9: View of Sheeter in Building 1B



Photo 10: View of Former Coating Machine Area on Second Floor of Building 1



**Photo 11: Adhesive Mixing Tank for One of Remaining Coating Machines in Plant
1**



**Photo 12: Sump in Basement of Building 1A and Adjacent Hydraulic Oil Tank
For Elevator On Right Side of Photo**